




Ponsard's Furnace-converters (Fig. 6-7) Fig. 10




Hofenanlage in St. Louis.





Gichtaufzug von Guyenet (Fig. 11-15)



Newer Modification des Whitwell-Apparates (Fig. 9-10)



Fabrikation von Stahlfedern in Forming (Fig. 5-8)



Verlag von Arthur Nebe in Leipzig

Lith. Anst. v. Steinmetz & Bernwardt, Berlin

