

Mass 873



6 in 2 Gang 12 Rippen p. Roll.

Stief 600 Maschine, 400/200 Platinen, 110/110 = 220 Zug.

I. Temp. Wolle, 1-2
400 Platinen, Plat:

I. Temp. Bindekette, 3
200 Platinen, Plat:

1. Gang Rippe	: Wolle lösen.	: Lurr.
2. 1. Schneidemas	: Roh, gold lösen.	: Roh, weifs lösen.



P 110