

20. Rauchfänge.

W. H. S.	W. H. S.	7399	W. H. S.	W. H. S.	7399
1/2		100	23		7.3407
1		200	1		7.5807
2		400	2		1 3.4215
3		600	3		1 11 2623
4		800	4		2 7 1031
5		1000	5		3 2.6838
6		1200	6		3 10.5246
7		1400	7		3 6.3654
8		1600	8		4 2 2062
9		1800	9		5 10 470
10		2000	10		6 5.6277
11		2200	20		12 11.5158
1		2400	30		19 5.4033
2		4800	40		1 11 2911
3		7200	50		1 8 5 1789
4		1 2201	60		1 14 11 667
5		1 4601	70		1 21 4.6844
6		1 7001	80		2 3 10.5822
7		2 2002	90		2 10 4.4700
8		2 4402	100		2 16 10.3578
9		2 6802	200		5 9 8.7156
10		3 1803	300		8 2 7 3335
11		3 4203	400		10 19 5.6913
12		3 6603	500		13 12 4 3092
13		4 1604	600		16 5 2.6670
14		4 4004	700		18 22 1 2849
15		4 6404	800		21 19 11.6427
16		5 1405	900		24 7 10 2606
17		5 3805	1000		27 - 8.6184
18		5 6205	2000		54 1 5.4969
19		6 1206	3000		81 2 2.3754
20		6 3606	4000		108 2 11 2539
21		6 6006	5000		135 3 8 1324
22		7 1007	6000		162 4 5 109