

Efsen, Axel

VIII 8° 2880,8: Spiral socket splices for deformed bars.  
København: Osterfeld 1957. 13 S. 8°  
(Laboratoriet for bygningstekn. Danmarks tekn. Højskole.  
Meddelelse Nr.8.)

VI 8° 5363 Splicing of cold-worked reinforcing bars by electric-arc  
welding.  
Liège: 1958:(Friedlaenders). 12 S. 8°

III/7/4 2815/57 1,00 10002 7

b.w.

VI 8° 5364 Bend Tests on danish tensor reinforcing bars, based on the ger-  
man code of practice.  
Liège: 1958:(Friedlaenders). 8 S. 8°

VIII 8° 2880,9: u. Herbert Krenchel:  
Tensile Cracks in reinforced concrete.  
København 1959. 24 S. 8°  
(Meddelelse Nr 9.)

6. 1. 1960