

			Zhl.	gl.	pf.	
4 Dertter=	Zangen	= = 16 lb. à lb. 1 gl. 6 pf.	1	—	—	
1 Stock=		= 3 lb. à = = =	—	4	6	
1 Beis=		= = = = = = =	—	8	—	
16 Spann=	Ringe	= = = = =	—	—	4	
1 Loch=		von 2 lb. à 1 gl. 6 gl. =	—	3	—	
1 Perl oder Possetell=	} Hammer, von 3 lb. à 2 gl. = = = = 1. 1/2 lb. à = = = = = = 3. 1/2 lb. à = = = = = = 2 lb. à = = = von 10 lb. à 2 gl. =	von 49 lb. à 2 gl. 6 pf. •	}	5	2	6
2 Schmiede=				—	6	—
1 Werk=				—	3	—
1 Plaz=				—	7	—
1 Böhrrer=				—	2	—
2 Dertter=		—	20	—		
1 Stock=	Schlag	= 8 = = = = =	—	16	—	
1 Seiten=		= 3 = = = = =	—	6	—	
1 Dertter=		von 2. 1/2 lb. à 1 gl. 9 pf.	—	4	4	
1 Feustel=	} Stempel	= 2 = = = = =	—	3	6	
1 Loch=		= 1. 1/2 = = = = =	—	2	7	
1 runder=		= 1. 1/2 = = = = =	—	2	7	
1 gevierdter=		= 4 = = = = =	—	7	—	
2 Sek=		= 1. 1/2 = à 3 gl. =	—	4	6	
3 Bergeisen=		—	4	—		
1 Dertterstöckel		von 2 lb. à 2 gl. = = =	—	8	—	
1 so. Hammerstühle,		= = = = = = =	4	—	—	
1 Schmiede=		von 6 lb. à 1 gl. 6 pf. =	—	9	—	
1 Helm=	Eisen	= 4 = = = = =	—	6	—	
1 Wende=		= 5 = à 2 gl. = = =	—	10	—	
2 Nagel=		= = = = = = =	—	6	—	
1 Zeichen=			—	6	—	
1 Kappeisen zum Schrauben,		von 4 lb. à 1 gl. 6 pf.	—	12	—	
2 Schneideböhrrer,		= = = = = = =	—	3	—	
1 Reifenzieher,		= = = = = = =	—	3	—	
1 Schröter, von 1 lb. à 3 gl.		= = = = = = =	—	12	—	
4 Lochdörner, von 4 lb.		= = = = = = =	—	4	—	
1 Raspel,		= = = = = = =	—	4	—	
1 Feile,		= = = = = = =	—	4	—	
1 Handbeil,		= = = = = = =	—	7	6	
1 Kluth=	Schaufel	von 5 lb. à 1 gl. 6 pf. =	—	4	6	
1 Köhl=		von 3 lb. à = = = = =	—	4	6	

1 Lösch=